

Michael O. Leavitt

# DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801 Governor (801) 538-5340 telephone Robert L. Morgan

(801) 359-3940 fax Executive Director Lowell P. Braxton (801) 538-7223 TTY

www.nr.utah.gov Division Director

**INSPECTION REPORT** 

Parti	al XXX Complete_	Exploration
ection Date:	12/20/2002 / Time:	11:00 am to 2:30 pm

Date of Last Inspection: 12/04/2002

Mine Name: Bear Canyon Mine County: Emery Permit Number: C/015/025							
Permittee and/or Operator's Name: Co-Op Mining Company							
Business Address: P.O. Box 1245, Huntington, Utah 84528							
Company Official(s): Mark Reynolds							
State Official(s): Mike Suflita Federal Official(s): None							
Weather Conditions: Snowing & Cold							
Type of Mining Activity: Underground XXX Surface Prep PlantOther							
Existing Acreage: Permitted 3336.18 Disturbed 37.17 Regraded Seeded Seeded							
Status: Active XXX							

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATED</b>	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	<u> </u>	$\Box$	[X]	$\Box$
3.	TOPSOIL		[X]	$\Box$	$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[ <u>X</u> ]		[X]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\Box$	[X]	$\Box$
c.	OTHER SEDIMENT CONTROL MEASURES		[X]	$\Box$	
d.	WATER MONITORING		[X]	$\Box$	$\Box$
e.	EFFLUENT LIMITATIONS		[X]	$\Box$	$\Box$
5.	EXPLOSIVES		[X]		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	[X]		
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\Box$	[X]	$\Box$	
8.	NONCOAL WASTE		$\Box$		
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	$\Box$	[X]		
10.	SLIDES AND OTHER DAMAGE		[X]	Ц	
11.	CONTEMPORANEOUS RECLAMATION		[X]		Щ
12.	BACKFILLING AND GRADING		[X]	Щ	ĻĻ
13.	REVEGETATION		[X]	$\Box$	ĻĻ
14.	SUBSIDENCE CONTROL	$\Box$	[X]		Ц
15.	CESSATION OF OPERATIONS		[X]	$\Box$	$\Box$
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]	$\Box$	[X]	Ц
b.	DRAINAGE CONTROLS		[X]		Ц
17.	OTHER TRANSPORTATION FACILITIES		[X]	$\Box$	$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	$\Box$	[ <u>X</u> ]	
19.	A S THE CK (4 <sup>th</sup> Quarter- April, May, June) AR GEALTPY PERMIT		[X]		Щ
20.	AR COALFY PERMIT		[X]		Ц
21.	BONDING & INSURANCE		[X]		$\Box$

#### INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/015/025</u>

DATE OF INSPECTION: 12/20/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

## 2. SIGNS AND MARKERS

The main sign at the mine entrance is in place along with Stream Buffer Zone, Substitute Topsoil Pile, and Topsoil Storage Pile signs.

### 4A. HYDROLOGIC BALANCE: DIVERSIONS

As much as possible with the snow, culverts and ditches were inspected and were found to have been cleaned out.

# 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Sediment pond A has ice and snow in it.

Pond B has ice and snow in it.

Pond C is has snow in it with no apparent sediment accumulation.

Sediment Pond D is not yet constructed at the top of the Wild Horse Ridge road.

#### 16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Roads were plowed and sanded. There are still typical winter conditions of packed snow and ice.

#### 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

Construction of the 3 portals at the top of Wild Horse Ridge is complete except for earth fill above the portals. There is an operational fan and mining has proceeded in two pillars. The steel work has begun to complete the tunnel connecting the conveyor belt to the portals. These last few hundred feet are expected to be finished by the end of the month. This will enable coal to be transported by conveyor all the way down the canyon.

Inspector's Signature:

Michael Suflita # 43

Date: December 26, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc:

James Fulton, OSM

Wendell Owen, Co-Op Mining

Price Field office

O:\015025.BCN\Compliance\2002\P\_1220.doc